



BCM

Product Change Notice

PCN Type: Hardware BIOS/Firmware Package/Label Driver OS Others Page: 1 of 1

PCN Number: 69033-P1-001/ 69034-P1-001/ 69030-P1-001/ 69031-P1-001		Revision: A		Date of Publication: 05/27/2014
PRODUCT NAME	PRODUCT PART#	OLD — REV. — NEW		REVISION TYPE
BI355-67QM	69033	1.1	1.1*	Labeling
BI355-67QM-RB	69034	1.1	1.1*	
BI255-255D	69030	1.1	1.2	
BI255-67QMD	69031	1.2	1.3	

REASON OF CHANGE:
Add FCC label to small batch/prototypes units assembled from local stock components at BCM's non-factory California location.

DESCRIPTION OF CHANGE:

- For BI355 series, add FCC/CE label for local build.
- For BI255 series, add FCC label for production and local build.

*Production build in factory has UL listed label already.

IMPACT OF CHANGE AND RECOMMEND ACTION:
This change has been thoroughly evaluated to ensure that there are no quality, reliability, functional, thermal or regulatory implications to our customers.
BCM is not recommending our customers to perform additional qualification of this change.

AFFECTED BY THIS CHANGE	
Specification	NO
Packaging	NO
Labeling	YES
BIOS	NO
Driver	NO
Hardware	NO

CUT IN DATE:
Date: 07/28/2014
OR
Lot#:
*Cut in date is based on the current forecast.

Parts Disposition	Rework	As Is	Scrap
New Order		X	
In Process		X	
Finished Goods		X	
RMA		X	

This PCN had been **QUALIFIED** and **APPROVED** by BCM Engineering Department on 05/27/2014.

APPROVED BY

VP OF SALES	<APPROVED>	05/27/2014
--------------------	------------	------------

Signature

Date