

## **BCM**

# **Product Change Notice**

PCN Type: ■HW/SYS/Kit □BIOS/LAN/FW □Package/Label □Driver/OS □Acc. □Others Page: 1 of 1

PCN Number: 71471-H1-002		Revision: A		Date of Publication: 11/18/2016	
PRODUCT NAME	PRODUCT PART#	OLD — REV. — NEW		REVISION TYPE	
MX110HD	71471-IA	1.0A	1.0B	Hardware	

#### **REASON OF CHANGE:**

To prevent the battery's cable blocking the card installation.

#### DESCRIPTION OF CHANGE:

Add the cable tie on the battery's cable.



### IMPACT OF CHANGE AND RECOMMEND ACTION:

This change has been thoroughly evaluated to ensure that there is no quality, reliability, functional, thermal or regulation implications to our customers.

BCM is not recommending our customers to perform additional qualification of this changes.

AFFECTED BY THIS CHANGE			
Specification	NO		
Packaging/ Accessory	NO		
Labeling	NO		
BIOS	NO		
Driver	NO		
Hardware	YES		

#### CUT IN DATE:

Date: Jan, 2016

OR **Lot#**:

\*Cut in date is based on the current forecast.

Parts Disposition	Rework	As Is	Scrap
New Order		X	
In Process		Х	
Finished Goods		Х	
RMA		Х	

This PCN had been QUALIFIED and APPROVED by BCM Engineering Department on 11/18/2016.

### **APPROVED BY**

VP OF SALES	<approved></approved>	11/18/2016
-------------	-----------------------	------------

Signature Date

Doc#: F-G0-0-005G