



# BCM

## Product Change Notice

PCN Type: Hardware BIOS/Firmware Package/Label Driver Others Page: 1 of 1

<b>PCN Number:</b> 71211-H1-009/ 71251-H1-003		<b>Revision:</b> A		<b>Date of Publication:</b> 08/31/2012
<b>PRODUCT NAME</b>	<b>PRODUCT PART#</b>	<b>OLD — REV. — NEW</b>		<b>REVISION TYPE</b>
MX45GM	71211-C	3.0	3.1	Hardware Revision
MX45GM2	71251-C	2.0	2.1	Hardware Revision

**REASON OF CHANGE:**

  
 JM micron JMB36X  
 EOL Letter 2012-04.z

JMicron part# JMB368 PATA host controller will be End of life on September 30<sup>th</sup>, 2012.

**DESCRIPTION OF CHANGE:**

- 1) Remove JM micron part# JMB368 and related parts.
- 2) Remove CF socket.

**IMPACT OF CHANGE AND RECOMMEND ACTION:**

This change has been thoroughly evaluated to ensure that there are no quality, reliability, functional or driver implications to our customers.

BCM is not recommending customers to perform additional qualification of these changes.

AFFECTED BY THIS CHANGE	
Specification	NO
Packaging	NO
Labeling	NO
BIOS	NO
Driver	NO
Hardware	YES

**CUT IN DATE:**

Date: 06/28/2013  
OR  
Lot#:

\*Cut in date is based on the current forecast.

Parts Disposition	Rework	As Is	Scrap
New Order		X	
In Process		X	
Finished Goods		X	
RMA		X	

This PCN had been **QUALIFIED** and **APPROVED** by BCM Engineering Department on 08/31/2012.

**APPROVED BY**

<b>VP OF SALES</b>	<APPROVED>	08/31/2012
	Signature	Date