



# BCM

## Product Change Notice

PCN Type: Hardware BIOS/Firmware Package/Label Driver Others Page: 1 of 1

<b>PCN Number:</b> 71111-H1-002		<b>Revision:</b> A		<b>Date of Publication:</b> 12/07/2010
<b>PRODUCT NAME</b>	<b>PRODUCT PART#</b>	OLD — REV. — NEW		<b>REVISION TYPE</b>
MX945GSE3	71111-C	1.0	1.1	Hardware Revision

**REASON OF CHANGE:**  
Winbond W83627DHG-A rev. UBC will be EOL.

**DESCRIPTION OF CHANGE:**  
Add Winbond W83627DHG-A rev. FAC in BOM/ AVL.

**IMPACT OF CHANGE AND RECOMMEND ACTION:**  
This change has been thoroughly evaluated to ensure that there are no quality, reliability, functional or driver implications to our customers.  
BCM is not recommending customers to perform additional qualification of these changes.  
It requires BIOS Rev. 1.02 or Up with this changes.

AFFECTED BY THIS CHANGE	
Specification	NO
Packaging	NO
Labeling	NO
BIOS	NO
Driver	NO
Hardware	YES

**CUT IN DATE:**  
**Date:** 01/03/2011 (Running Changes)  
OR  
**Lot#:**  
\*Cut in date is based on the current forecast.

This PCN had been **QUALIFIED** and **APPROVED** by BCM Engineering Department on 11/11/2010.

**APPROVED BY**

<b>CUSTOMER/ VP OF SALES</b>	<APPROVED>	12/07/2010
----------------------------------	------------	------------

Signature

Date