



BCM

Product Change Notice

PCN Type : Hardware BIOS/Firmware Test Driver Others Page: 1 of 1

ECO Number: 70651-B1-007 Revision: A Issued Date: 05/28/2010

Drawing Number	OLD	REV.	NEW	TITLE	MODEL
70651	1.05	1.06		RX35Q (#70651) BIOS	RX35Q

REASON:
Update CPU micro code to include support for the latest Intel® Core™2 Duo E8xxx processors.

DESCRIPTION OF CHANGE:
File Name: 70651106.rom
BIOS ver: 1.06
Build date: 03/12/2010
BIOS message: RX35Q BIOS Ver 1.06
BIOS Checksum: 9fb3 hex

IMPACT OF CHANGE AND RECOMMEND ACTION:
This change has been thoroughly evaluated to ensure that there are no quality, reliability, functional or driver implications to our customers.
BCM is not recommending additional qualification of these changes on the board.

CLASS OF CHANGE	AFFECTED BY THIS CHANGE			PARTS DISPOSITION	REWORK	USE AS	SCRAP	EFFECTIVITY
X A-MANDATORY	X REC INSPECTION		TEST EQUIP.	NEW ORDER		X		DATE: OR LOT: 1032 OR SERIAL No. : _____
B-RECORD	TEST PROCEDURES		TOOLING	IN PROCESS		X		
C-DEVIATION	MFG. RWK. INSTR.			FINISHED GOODS		X		
Project Control Number: 70651-B1-007				CUSTOMER		X		
				RMA		X		

Originator: William Huang Department: Engineering Phone: 949-470-1888 Ext. 273 Date: 05/28/2010

Department	Signatures	Date	Department	Signatures	Date
PROJECT ENGINEER	William Huang	05/28/2010	ACCOUNT MANAGER	Jennifer Morris	05/28/2010
R&D MANAGER	William Huang	05/28/2010	SALES MANAGER	Tom Skibinski	05/28/2010
PROJECT MANAGER	Laurent Liu	05/28/2010			

Approved By

CUSTOMER/ VP OF SALES		
--------------------------	--	--

Signature

Date