



BCM

Product Change Notice

PCN Type : Hardware BIOS/Firmware Test Driver Others Page: 1 of 1

ECO Number: 70651-H1-002		Revision: A	Issued Date: 05/28/2010
Drawing Number	OLD—REV. --NEW	TITLE	MODEL
70650-001	1.0 1.0	PWB	RX35Q
70651-001	1.0 1.1	PWA	RX35Q
70651-002	1.0 1.1	BOM/ AVL	RX35Q

REASON:
Improved power supply compatibility.

DESCRIPTION OF CHANGE:

- Change Q8 from MMBT3904 type to MMBT7002 type.
- Change R67 from 20k ohm to 4.7k ohm.
- Change R275 from 1k ohm to 4.7k ohm.

IMPACT OF CHANGE AND RECOMMEND ACTION:

This change has been thoroughly evaluated to ensure that there are no quality, reliability, functional or driver implications to our customers.

BCM is not recommending customers to perform additional qualification of these changes.

CLASS OF CHANGE	AFFECTED BY THIS CHANGE			PARTS DISPOSITION	REWORK	USE AS	SCRAP	EFFECTIVITY
X A-MANDATORY	X REC INSPECTION	TEST EQUIP.	NEW ORDER	X				DATE:
B-RECORD	TEST PROCEDURES	TOOLING	IN PROCESS	X				OR
C-DEVIATION	MFG. RWK. INSTR.		FINISHED GOODS		X			LOT: 1037
Project Control Number: 70651-H1-002				CUSTOMER		X		OR
				RMA		X		SERIAL No. : _____
Originator: William Huang		Department: Engineering		Phone: 949-470-1888 Ext. 273			Date: 05/28/2010	

Department	Signatures	Date	Department	Signatures	Date
PROJECT ENGINEER	William Huang	05/28/2010	ACCOUNT MANAGER	Jennifer Morris	05/28/2010
R&D MANAGER	William Huang	05/28/2010	SALES MANAGER	Tom Skibinski	05/28/2010
PROJECT MANAGER	Laurent Liu	05/28/2010			

Approved By

CUSTOMER/ VP OF SALES		
--------------------------	--	--

Signature

Date