



BCM

Product Change Notice

PCN Type: Hardware BIOS/Firmware Package/Label Driver OS Others Page: 1 of 1

PCN Number: 70813-B1-002		Revision: A		Date of Publication: 05/30/2013
PRODUCT NAME	PRODUCT PART#	OLD — REV. — NEW		REVISION TYPE
BC67Q	70813-C	1.02	1.03	BIOS

REASON OF CHANGE:
 Corrects a typo in the BIOS display string pertaining to the BCM motherboard part number.

DESCRIPTION OF CHANGE:
 File Name: 70813213.bin
 Message: BC67Q (70813) BIOS Ver 1.03
 Version #: 1.03
 Date: 03/19/2013
 Checksum: d5f2 hex
 Flash Utility: AMI Firmware Update Utility v3.01.00 (AFUDOS.exe)

IMPACT OF CHANGE AND RECOMMEND ACTION:
 This change has been thoroughly evaluated to ensure that there are no quality, reliability or functional implications to our customers.
 BCM is not recommending customers to perform additional qualification of this changes.

AFFECTED BY THIS CHANGE	
Specification	NO
Packaging	NO
Labeling	NO
BIOS	YES
Driver	NO
Hardware	NO

CUT IN DATE:
 Date: 07/08/2013
 OR
 Lot#:
 *Cut in date is based on the current forecast.

Parts Disposition	Rework	As Is	Scrap
New Order	X		
In Process	X		
Finished Goods	X		
RMA		X	

This PCN had been **QUALIFIED** and **APPROVED** by BCM Engineering Department on 03/21/2013.

APPROVED BY

VP OF SALES	<APPROVED>	03/28/2013
--------------------	------------	------------

Signature

Date