



BCM

Product Change Notice

PCN Type: HW/SYS/Kit BIOS/LAN/FW Package/Label Driver/OS Acc. Others Page: 1 of 1


PCN Number: 71001-H1-007		Revision: A		Date of Publication: 11/17/2016
PRODUCT NAME	PRODUCT PART#	OLD — REV. — NEW		REVISION TYPE
MX1900J	71001-IA	1.4	1.4A	Hardware

REASON OF CHANGE:
 Improve the pigtail type battery's adhesiveness to the motherboard.

DESCRIPTION OF CHANGE:
 Change the battery adhesive location:
 From



To



IMPACT OF CHANGE AND RECOMMEND ACTION:
 This change has been thoroughly evaluated to ensure that there is no quality, reliability, functional, thermal or regulation implications to our customers.

BCM is not recommending our customers to perform additional qualification of these changes.

AFFECTED BY THIS CHANGE	
Specification	NO
Packaging	NO
Labeling	NO
BIOS	NO
Driver	NO
Hardware	YES

CUT IN DATE:

Date: Jan, 2017

OR

Lot#:

*Cut in date is based on the current forecast.

Parts Disposition	Rework	As Is	Scrap
New Order		X	
In Process		X	
Finished Goods		X	
RMA		X	

This PCN had been **QUALIFIED** and **APPROVED** by BCM Engineering Department on 11/17/2016.

APPROVED BY

VP OF SALES	<APPROVED>	11/17/2016
-------------	------------	------------

Signature

Date