



BCM

Product Change Notice

PCN Type: HW/SYS/Kit BIOS/LAN/FW Package/Label Driver/OS Acc. Others Page: 1 of 1

PCN Number: 70961-B1-003		Revision: A		Date of Publication: 02/12/2016
PRODUCT NAME	PRODUCT PART#	OLD — REV. — NEW		REVISION TYPE
MX280NI	70961-IA	1.02	1.03	BIOS

REASON OF CHANGE:
 BIOS update to address Ubuntu 14.04.2 performance issues reported from the field.

DESCRIPTION OF CHANGE:
 File name: 70961103.ROM
 Message: MX280NI #70961 BIOS V1.03
 Version: 1.03
 Date: 02/05/2016
 Checksum: 06A7 hex
 Flash Utility: Built into the UEFI BIOS

IMPACT OF CHANGE AND RECOMMEND ACTION:
 This change has been thoroughly evaluated to ensure that there are no quality and functional implications to our customers.
 BCM is recommending customers to perform additional qualification of this change.

AFFECTED BY THIS CHANGE	
Specification	NO
Packaging	NO
Labeling	NO
BIOS	YES
Driver	NO
Hardware	NO

CUT IN DATE:
 Date: 03/28/2016
 OR
 Lot#:

*Cut in date is based on the current forecast.

Parts Disposition	Rework	As Is	Scrap
New Order	X		
In Process		X	
Finished Goods		X	
RMA		X	

This PCN had been **QUALIFIED** and **APPROVED** by BCM Engineering Department on 02/05/2016.

APPROVED BY

VP OF SALES	<APPROVED>	02/05/2016
--------------------	------------	------------

Signature

Date