



BCM

Product Change Notice


PCN Type: HW/SYS/Kit BIOS/LAN/FW Package/Label Driver/OS Acc. Others Page: 1 of 2

PCN Number: P204401		Revision: A		Date of Publication: 10/27/2020
PRODUCT NAME	PRODUCT PART#	OLD — REV. — NEW		REVISION TYPE
MX310HD	71641-IA	1.0	1.0A	Accessory


REASON OF CHANGE:
 Increase length of SATA power cable and add a second SATA power connector to accommodate a greater variance in enclosure sizes.

DESCRIPTION OF CHANGE:
 Change the SATA power cable length from 400mm to 800mm. Add second SATA power connector.

From:



To:



IMPACT OF CHANGE AND RECOMMEND ACTION:

This change has been thoroughly evaluated to ensure that there are no quality and regulation implications to our customer.

BCM is not recommending customer to perform additional qualification of this change.

AFFECTED BY THIS CHANGE	
Specification	NO
Accessory	YES
Labeling	NO
BIOS	NO
Driver	NO
Hardware	NO

CUT IN DATE:

Date: February, 2020

OR

Lot#:

*Cut in date is based on the current forecast.

Parts Disposition	Rework	As Is	Scrap
New Order	X		
In Process		X	
Finished Goods		X	
RMA		X	

This PCN had been **QUALIFIED** and **APPROVED** by BCM Operations Department on 10/27/2020.

This PCN had been **APPROVED** by BCM Procurement Department on October, 2020.

APPROVED BY

VP OF SALES	<APPROVED>	10/27/2020
--------------------	------------	------------

Signature

Date