



BCM

Product Change Notice

PCN Type: HW/SYS/Kit BIOS/LAN/FW Package/Label Driver/OS Acc. Others Page: 1 of 1

PCN Number: 70903-B1-002		Revision: A		Date of Publication: 09/26/2014
PRODUCT NAME	PRODUCT PART#	OLD — REV. — NEW		REVISION TYPE
RX87Q	70903-C	1.00	1.01	BIOS

REASON OF CHANGE:

- 1) Improve compatibility with a broader range of PCIe cards.
- 2) Address the possible screen corruption issue when booting to a UEFI environment with a USB key.

DESCRIPTION OF CHANGE:

File name 70903100.rom
 Message: RX87Q (70903) BIOS V1.01
 Version: 1.01
 Build Date: 07/30/2014
 Checksum: 299C hex
 Flash Utility: AMI Firmware Update Utility v2.31 (afudos.exe)

IMPACT OF CHANGE AND RECOMMEND ACTION:

This change has been thoroughly evaluated to ensure that there is no quality, reliability, functional or driver implications to our customers.

BCM is not recommending our customers to perform additional qualification of this changes.

AFFECTED BY THIS CHANGE	
Specification	NO
Packaging	NO
Labeling	NO
BIOS	YES
Driver	NO
Hardware	NO

CUT IN DATE:

Date: 11/24/2014
 OR
 Lot#:

*Cut in date is based on the current forecast.

Parts Disposition	Rework	As Is	Scrap
New Order		X	
In Process		X	
Finished Goods		X	
RMA		X	

This PCN had been **QUALIFIED** and **APPROVED** by BCM Engineering Department on 09/26/2014.

APPROVED BY

VP OF SALES	<APPROVED>	09/26/2014
--------------------	------------	------------

Signature

Date